





Tel: 02867737177
Fax:
Email Sales@fbbarriers.co.uk
Web: www.fbbarriers.co.uk

Title	Remedial/ Extension	Products:	Fix Detail: 15
		All products excluding FB 60-60 60-60	Version: 2
TPA ref			Date: 31/07/2025



If overlap is too short, add
a suitably sized section and fix
to the existing barrier as
shown in panel.

#	DESCRIPTION	NOTES
1	Overlap too short	
2	50 x 25mm galv angle	
3	25 x 25mm galv angle	
4	Inserted section of barrier	
5	100mm overlap	
6	50mm butt joint seam	
7	Steel screw	200mm centres



Minimum of 50mm butt joint
from each barrier with two
rows of staples, staggered